

Cat Electronic Technician 2014C v1.0 Logged Event Code

7/7/2015 1:26 PM

Comments:

STD00214 C18 Logged Events

EMCP 3.2

Parameter	Value
ECM Part Number	2275801-05
ECM Serial Number	2966B189HQ
Software Group Part Number	3041337-00
Software Group Release Date	OCT2006
Software Group Description	L1_4_5_Standard -- English, 2.1 Prod, 26Oct2006

Code	Description	Occur
EMCP 3.2 SMH: 684 RTC: 7/27/1930 2:24:44 PM		
970-31	Engine Auxiliary Engine Shutdown Switch	31
SMH First: 118:01:25 SMH Last: 683:46:30		
RTC First: 5/13/2011 8:34:28 AM RTC Last: 7/7/2015 2:03:14 PM		
168-17	Battery Potential / Power Input #1 : Low - least severe (1)	7
SMH First: 683:17:11 SMH Last: 683:31:30		
RTC First: 9/29/2011 3:39:01 PM RTC Last: 10/29/2014 10:54:31 AM		
4007-31	Generator Control not in Automatic	99
SMH First: 0:00:00 SMH Last: 683:31:30		
RTC First: 11/30/1984 RTC Last: 10/23/2014 3:19:39 PM		
110-17	Engine Coolant Temperature : Low - least severe (1)	99
SMH First: 118:01:30 SMH Last: 683:17:11		
RTC First: 5/23/2011 2:12:16 PM RTC Last: 9/27/2011 1:10:12 PM		
1664-31	Engine Automatic Start Failed	1
SMH First: 68:58:32 SMH Last: 68:58:32		

RTC First: 9/1/2009 9:49:09 AM RTC Last: 9/1/2009 9:49:09 AM		
167-17	Charging System Potential : Low - least severe (1)	99
SMH First: 31:06:32 SMH Last: 33:42:35		
RTC First: 6/7/2008 1:36:09 PM RTC Last: 7/12/2008 2:04:18 PM		
168-15	Battery Potential / Power Input #1 : High - least severe (1)	2
SMH First: 18:19:16 SMH Last: 18:50:29		
RTC First: 12/25/2007 9:21:32 AM RTC Last: 1/1/2008 9:21:19 AM		